

Příloha 3 – Korespondence s firmou Honeywell

Dear Karel,

Thanks for contact Honeywell Aero Technical Support Organization.

I received your technical requirement related chapter 36 for B737NG fleet.

For your information and reference related those particular Honeywell part numbers, please be notified that Honeywell didn't assign any hard time. Those components are considered under ON CONDITION criteria.

Nevertheless, please receive current estimated MTTF for your reference.

Precooler Control Valve P/N 3289562-6 or -7 , MTTF 10650 . Observe that this value due to new PCCV being released , MTTF data is no accurate, because there is not way to split the flight hours up accurately between the 2 outlines. This is just for your reference only.

High Stage Valve P/N 3214446-4, MTTF 20000

PRSOV P/N 3214552-5 and -6 , MTTF 12600

Hoping provided information helps.

Thank you and Best Regards,

Claudia Flores

Aerospace Technical Support Engineer

C&PS Technical Operations
Honeywell Aerospace
1-855-808-6500 (US/CAN)
1-602-365-6500 (INTL)

AeroTechSupport@Honeywell.com