

Datum: 20.10.2022

Místo: Štěpánská

Směr: Karlovo náměstí

Linka	Prav. odj.	Skut. odj.	Zpoždění	Vozidlo	Celkem	Obsazenost %
16	7:04	7:05:06	01:06	T3	61	46,9
22	7:04	7:05:01	01:01	T3	83	63,8
4	7:05	7:06:04	01:04	T3	24	18,5
6	7:07	7:07:51	00:51	15T	49	35,0
10	7:08	7:07:54		T3	63	48,5
22	7:08	7:08:51	00:51	T3	70	53,8
16	7:12	7:14:42	02:42	KT	131	100,8
22	7:12	7:13:14	01:14	T3	112	86,2
4	7:15	7:15:59	00:59	15T	58	41,4
6	7:15	7:16:38	01:38	15T	64	45,7
10	7:16	7:17:05	01:05	T3	29	22,3
22	7:16	7:18:36	02:36	15T	103	73,6
16	7:20	7:21:06	01:06	T3	128	98,5
22	7:20	7:20:02	00:02	T3	45	34,6
4	7:23	7:23:03	00:03	15T	70	50,0
6	7:23	7:26:07	03:07	T3	48	36,9
10	7:24	7:24:08	00:08	15T	60	42,9
22	7:24	7:26:18	02:18	T3	121	93,1
16	7:28	7:27:59		15T	137	97,9
22	7:28	7:28:16	00:16	15T	63	45,0
4	7:31	7:35:07	04:07	T3	67	51,5
6	7:31	7:34:02	03:02	T3	86	66,2
10	7:32	7:33:04	01:04	T3	128	98,5
22	7:32	7:34:23	02:23	T3	133	102,3
16	7:36	7:40:06	04:06	KT	102	78,5
22	7:36	7:38:27	02:27	T3	130	100,0
4	7:39	7:39:06	00:06	15T	48	34,3
6	7:39	7:39:49	00:49	KT	116	89,2
10	7:40	7:41:06	01:06	15T	70	50,0
22	7:40	7:42:32	02:32	T3	134	103,1
16	7:44	7:45:10	01:10	15T	146	104,3
22	7:44	7:50:21	06:21	T3	146	112,3
4	7:47	7:51:10	04:10	15T	55	39,3
6	7:47	7:50:53	03:53	T3	85	65,4
10	7:48	7:49:08	01:08	15T	119	85,0
22	7:48	7:55:59	07:59	15T	131	93,6
23	7:50	7:52:14	02:14	1xT3	65	100,0
16	7:52	7:53:07	01:07	T3	67	51,5
22	7:52	7:58:09	06:09	15T	117	83,6
4	7:55	7:59:32	04:32	15T	103	73,6
6	7:55	7:56:57	01:57	T3	84	64,6
10	7:56	7:56:22	00:22	15T	64	45,7
22	7:56	8:01:09	05:09	15T	68	48,6