

Datum: 20.10.2022

Místo: Štěpánská

Směr: I. P. Pavlova

Linka	Prav. odj.	Skut. odj.	Zpoždění	Vozidlo	Celkem	Obsazenost %
16	15:01	15:03:55	02:55	15T	101	72,1
22	15:02	15:04:44	02:44	T3	70	53,8
10	15:06	15:08:54	02:54	15T	134	95,7
22	15:07	15:11:48	04:48	T3	128	98,5
6	15:08	15:11:07	03:07	T3	99	76,2
16	15:11	15:12:02	01:02	T3	82	63,1
22	15:12	15:16:04	04:04	KT	63	48,5
4	15:13	15:15:39	02:39	15T	62	44,3
10	15:16	15:16:47	00:47	T3	80	61,5
22	15:17	15:24:21	07:21	15T	143	102,1
6	15:18	15:19:13	01:13	T3	79	60,8
4	15:19	15:19:48	00:48	T3	42	32,3
16	15:21	15:22:49	01:49	KT	91	70,0
22	15:21	15:24:53	03:53	15T	67	47,9
10	15:25	15:26:43	01:43	T3	134	103,1
22	15:25	15:27:27	02:27	15T	57	40,7
6	15:26	15:29:45	03:45	15T	98	70,0
23	15:28	15:29:06	01:06	1xT3	31	47,7
4	15:29	15:30:46	01:46	T3	71	54,6
16	15:29	15:32:09	03:09	T3	54	41,5
22	15:29	15:32:14	03:14	T3	102	78,5
10	15:33	15:34:49	01:49	15T	130	92,9
22	15:33	15:35:29	02:29	15T	90	64,3
6	15:34	15:37:15	03:15	T3	81	62,3
4	15:35	15:38:57	03:57	15T	79	56,4
16	15:37	15:40:47	03:47	15T	88	62,9
22	15:37	15:40:12	03:12	15T	140	100,0
10	15:41	15:42:48	01:48	15T	98	70,0
22	15:41	15:44:35	03:35	T3	104	80,0
6	15:42	15:43:49	01:49	15T	74	52,9
4	15:42	15:43:55	01:55	15T	42	30,0
16	15:45	15:45:43	00:43	T3	59	45,4
22	15:45	15:47:00	02:00	T3	87	66,9
10	15:49	15:50:03	01:03	T3	128	98,5
22	15:49	15:51:58	02:58	T3	127	97,7
6	15:50	15:56:17	06:17	T3	96	73,8
4	15:52	15:52:41	00:41	15T	76	54,3
16	15:53	15:57:08	04:08	15T	117	83,6
22	15:53	15:55:21	02:21	T3	123	94,6
23	15:56	15:57:14	01:14	1xT3	42	64,6
10	15:57	15:59:12	02:12	15T	141	100,7
22	15:57	15:58:53	01:53	15T	119	85,0
6	15:58	16:02:43	04:43	15T	102	72,9
4	15:59	16:01:42	02:42	15T	82	58,6