

Datum: 25.04.2023

Místo: Štěpánská

Směr: I. P. Pavlova

Linka	Prav. odj.	Skut. odj.	Zpoždění	Vozidlo	Celkem	Obsazenost %
22	20:00	20:03:07	03:07	15T	101	72,1
16	20:04	20:09:50	05:50	KT	110	84,6
22	20:08	20:10:10	02:10	T3	86	66,2
10	20:11	20:12:04	01:04	15T	89	63,6
6	20:11	20:12:50	01:50	15T	109	77,9
22	20:15	20:16:59	01:59	T3	100	76,9
16	20:19	20:21:54	02:54	KT	115	88,5
22	20:23	20:24:02	01:02	T3	112	86,2
10	20:26	20:28:47	02:47	15T	121	86,4
6	20:26	20:27:01	01:01	15T	106	75,7
22	20:30	20:31:04	01:04	T3	96	73,8
16	20:34	20:34:49	00:49	KT	76	58,5
22	20:38	20:39:08	01:08	T3	110	84,6
10	20:41	20:45:45	04:45	15T	105	75,0
6	20:41	20:44:10	03:10	15T	73	52,1
22	20:45	20:46:44	01:44	T3	105	80,8
16	20:49	20:50:51	01:51	T3	83	63,8
22	20:53	20:55:11	02:11	T3	102	78,5
10	20:56	20:57:53	01:53	15T	109	77,9
6	20:56	20:56:58	00:58	15T	83	59,3