



ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**

Last 1 measurements

► Approval ≠ locked

Drawing number

Variant

Department

Measurement number

1

Order number

Time/Date

14.7.2021 8:29

Gage equipment

UPMC_8_C

Run

Všechny charakteris...

Operator

Master

No. measured values

220

Text

No. values error

● 110



























































































Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
Průměr_Kružnice1(1)	19.7715	20.0000			-0.2285 ●	
Průměr_Kružnice1(2)	19.8174	20.0000			-0.1826 ●	
Průměr_Kružnice1(3)	19.8517	20.0000			-0.1483 ●	
Průměr_Kružnice1(4)	19.8161	20.0000			-0.1839 ●	
Průměr_Kružnice1(5)	19.8222	20.0000			-0.1778 ●	
Průměr_Kružnice1(6)	19.8312	20.0000			-0.1688 ●	
Průměr_Kružnice1(7)	19.8278	20.0000			-0.1722 ●	
Průměr_Kružnice1(8)	19.8268	20.0000			-0.1732 ●	
Průměr_Kružnice1(9)	19.8052	20.0000			-0.1948 ●	
Průměr_Kružnice1(10)	19.7736	20.0000			-0.2264 ●	
Průměr_Kružnice1(11)	19.7593	20.0000			-0.2407 ●	
Průměr_Kružnice1(12)	19.7556	20.0000			-0.2444 ●	
Průměr_Kružnice1(13)	19.7698	20.0000			-0.2302 ●	
Průměr_Kružnice1(14)	19.8069	20.0000			-0.1931 ●	
Průměr_Kružnice1(15)	19.8206	20.0000			-0.1794 ●	
Průměr_Kružnice1(16)	19.8132	20.0000			-0.1868 ●	
Průměr_Kružnice1(17)	19.8027	20.0000			-0.1973 ●	
Průměr_Kružnice1(18)	19.8181	20.0000			-0.1819 ●	
Průměr_Kružnice1(19)	19.8091	20.0000			-0.1909 ●	
Průměr_Kružnice1(20)	19.7966	20.0000			-0.2034 ●	
Průměr_Kružnice1(21)	19.7871	20.0000			-0.2129 ●	
Průměr_Kružnice1(22)	19.7900	20.0000			-0.2100 ●	
Průměr_Kružnice1(23)	19.7190	20.0000			-0.2810 ●	
Průměr_Kružnice1(24)	19.7620	20.0000			-0.2380 ●	



ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
 Průměr_Kružnice1(25)	19.8008	20.0000			-0.1992 	
 Průměr_Kružnice1(26)	19.8173	20.0000			-0.1827 	
 Průměr_Kružnice1(27)	19.7915	20.0000			-0.2085 	
 Průměr_Kružnice1(28)	19.8255	20.0000			-0.1745 	
 Průměr_Kružnice1(29)	19.8124	20.0000			-0.1876 	
 Průměr_Kružnice1(30)	19.8049	20.0000			-0.1951 	
 Průměr_Kružnice1(31)	19.8008	20.0000			-0.1992 	
 Průměr_Kružnice1(32)	19.7571	20.0000			-0.2429 	
 Průměr_Kružnice1(33)	19.7478	20.0000			-0.2522 	
 Průměr_Kružnice1(34)	19.7366	20.0000			-0.2634 	
 Průměr_Kružnice1(35)	19.7579	20.0000			-0.2421 	
 Průměr_Kružnice1(36)	19.7909	20.0000			-0.2091 	
 Průměr_Kružnice1(37)	19.7659	20.0000			-0.2341 	
 Průměr_Kružnice1(38)	19.7809	20.0000			-0.2191 	
 Průměr_Kružnice1(39)	19.7812	20.0000			-0.2188 	
 Průměr_Kružnice1(40)	19.8229	20.0000			-0.1771 	
 Průměr_Kružnice1(41)	19.8005	20.0000			-0.1995 	
 Průměr_Kružnice1(42)	19.8162	20.0000			-0.1838 	
 Průměr_Kružnice1(43)	19.7578	20.0000			-0.2422 	
 Průměr_Kružnice1(44)	19.7356	20.0000			-0.2644 	
 Průměr_Kružnice1(45)	19.6633	20.0000			-0.3367 	
 Průměr_Kružnice1(46)	19.7010	20.0000			-0.2990 	
 Průměr_Kružnice1(47)	19.7332	20.0000			-0.2668 	
 Průměr_Kružnice1(48)	19.7187	20.0000			-0.2813 	
 Průměr_Kružnice1(49)	19.7795	20.0000			-0.2205 	
 Průměr_Kružnice1(50)	19.7991	20.0000			-0.2009 	
 Průměr_Kružnice1(51)	19.7984	20.0000			-0.2016 	
 Průměr_Kružnice1(52)	19.7998	20.0000			-0.2002 	
 Průměr_Kružnice1(53)	19.7997	20.0000			-0.2003 	
 Průměr_Kružnice1(54)	19.7928	20.0000			-0.2072 	



ZEISS CALYPSO

6.0.28


Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----

Průměr_Kružnice1(55)	19.7878	20.0000			-0.2122	
----------------------	---------	---------	--	--	---------	--


Kruhovitost_Kružnice1(1)	0.5064	0.0000	0.0000	0.0000	0.5064		0.5064
--------------------------	--------	--------	--------	--------	--------	--	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




Kruhovitost_Kružnice1(2)	0.6603	0.0000	0.0000	0.0000	0.6603		0.6603
--------------------------	--------	--------	--------	--------	--------	--	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



Kruhovitost_Kružnice1(3)	0.6480	0.0000	0.0000	0.0000	0.6480		0.6480
--------------------------	--------	--------	--------	--------	--------	--	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(4)	0.7621	0.0000	0.0000	0.0000	0.7621	0.7621
--	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(5)	0.9181	0.0000	0.0000	0.0000	0.9181	0.9181
--	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(6)	0.8737	0.0000	0.0000	0.0000	0.8737	0.8737
--	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(7)	0.8340	0.0000	0.0000	0.0000	0.8340	0.8340
--	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(8)	0.8680	0.0000	0.0000	0.0000	0.8680	0.8680
--	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(9)	0.8718	0.0000	0.0000	0.0000	0.8718	0.8718
--	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(10)	0.6368	0.0000	0.0000	0.0000	0.6368	0.6368
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(11)	0.6675	0.0000	0.0000	0.0000	0.6675	0.6675
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(12)	0.4795	0.0000	0.0000	0.0000	0.4795	0.4795
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(13)	1.0044	0.0000	0.0000	0.0000	1.0044	1.0044
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(14)	0.6627	0.0000	0.0000	0.0000	0.6627	0.6627
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(15)	0.7518	0.0000	0.0000	0.0000	0.7518	0.7518
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(16)	0.9300	0.0000	0.0000	0.0000	0.9300	0.9300
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(17)	0.8911	0.0000	0.0000	0.0000	0.8911	0.8911
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(18)	0.8761	0.0000	0.0000	0.0000	0.8761	0.8761
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(19) Points 468 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.8661	0.0000	0.0000	0.0000	0.8661	0.8661
<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(20) Points 468 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.7311	0.0000	0.0000	0.0000	0.7311	0.7311
<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(21) Points 468 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.7101	0.0000	0.0000	0.0000	0.7101	0.7101



ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(22)	0.5868	0.0000	0.0000	0.0000	0.5868	0.5868
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(23)	0.6185	0.0000	0.0000	0.0000	0.6185	0.6185
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(24)	0.7365	0.0000	0.0000	0.0000	0.7365	0.7365
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(25)	0.7925	0.0000	0.0000	0.0000	0.7925	0.7925
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(26)	0.7242	0.0000	0.0000	0.0000	0.7242	0.7242
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(27)	0.8362	0.0000	0.0000	0.0000	0.8362	0.8362
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(28)	0.8012	0.0000	0.0000	0.0000	0.8012	0.8012
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(29)	0.8518	0.0000	0.0000	0.0000	0.8518	0.8518
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(30)	0.8316	0.0000	0.0000	0.0000	0.8316	0.8316
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(31)	0.7956	0.0000	0.0000	0.0000	0.7956	0.7956
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(32)	0.6035	0.0000	0.0000	0.0000	0.6035	0.6035
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(33)	0.4928	0.0000	0.0000	0.0000	0.4928	0.4928
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(34)	0.4576	0.0000	0.0000	0.0000	0.4576	0.4576
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(35)	0.7228	0.0000	0.0000	0.0000	0.7228	0.7228
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(36)	0.7621	0.0000	0.0000	0.0000	0.7621	0.7621
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(37)	0.7705	0.0000	0.0000	0.0000	0.7705	0.7705
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(38)	0.7836	0.0000	0.0000	0.0000	0.7836	0.7836
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(39)	0.7723	0.0000	0.0000	0.0000	0.7723	0.7723
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(40)	0.7703	0.0000	0.0000	0.0000	0.7703	0.7703
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(41)	0.7517	0.0000	0.0000	0.0000	0.7517	0.7517
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(42)	0.5042	0.0000	0.0000	0.0000	0.5042	0.5042
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(43)	0.6143	0.0000	0.0000	0.0000	0.6143	0.6143
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(44)	0.5089	0.0000	0.0000	0.0000	0.5089	0.5089
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(45)	0.4307	0.0000	0.0000	0.0000	0.4307	0.4307
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(46)	0.5177	0.0000	0.0000	0.0000	0.5177	0.5177
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(47)	0.6416	0.0000	0.0000	0.0000	0.6416	0.6416
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(48)	0.6136	0.0000	0.0000	0.0000	0.6136	0.6136
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(49)	0.6693	0.0000	0.0000	0.0000	0.6693	0.6693
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(50)	0.7055	0.0000	0.0000	0.0000	0.7055	0.7055
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(51)	0.6947	0.0000	0.0000	0.0000	0.6947	0.6947
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(52)	0.6895	0.0000	0.0000	0.0000	0.6895	0.6895
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(53)	0.5816	0.0000	0.0000	0.0000	0.5816	0.5816
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice1(54)	0.5577	0.0000	0.0000	0.0000	0.5577	0.5577
---	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----

Kruhovitost_Kružnice1(55)	0.4898	0.0000	0.0000	0.0000	0.4898	0.4898
---------------------------	--------	--------	--------	--------	--------	--------

Points 468
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



Průměr_Kružnice2(1)	19.8903	20.0000			-0.1097	
Průměr_Kružnice2(2)	19.9700	20.0000			-0.0300	
Průměr_Kružnice2(3)	20.0250	20.0000			0.0250	
Průměr_Kružnice2(4)	19.9718	20.0000			-0.0282	
Průměr_Kružnice2(5)	20.0110	20.0000			0.0110	
Průměr_Kružnice2(6)	20.0067	20.0000			0.0067	
Průměr_Kružnice2(7)	19.9962	20.0000			-0.0038	
Průměr_Kružnice2(8)	20.0025	20.0000			0.0025	
Průměr_Kružnice2(9)	19.9810	20.0000			-0.0190	
Průměr_Kružnice2(10)	19.8776	20.0000			-0.1224	
Průměr_Kružnice2(11)	19.8405	20.0000			-0.1595	
Průměr_Kružnice2(12)	19.8131	20.0000			-0.1869	
Průměr_Kružnice2(13)	19.8976	20.0000			-0.1024	
Průměr_Kružnice2(14)	19.9288	20.0000			-0.0712	
Průměr_Kružnice2(15)	19.9039	20.0000			-0.0961	
Průměr_Kružnice2(16)	19.9093	20.0000			-0.0907	
Průměr_Kružnice2(17)	19.9301	20.0000			-0.0699	
Průměr_Kružnice2(18)	19.9679	20.0000			-0.0321	
Průměr_Kružnice2(19)	19.8674	20.0000			-0.1326	
Průměr_Kružnice2(20)	19.9041	20.0000			-0.0959	
Průměr_Kružnice2(21)	19.8570	20.0000			-0.1430	


























































































ZEISS CALYPSO

6.0.28

Part name
Measurement number
Operator
Time/Date

plech_diry_rastr 11x5
1
Master
14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
 Průměr_Kružnice2(22)	19.8631	20.0000			-0.1369 	
 Průměr_Kružnice2(23)	19.7950	20.0000			-0.2050 	
 Průměr_Kružnice2(24)	19.8698	20.0000			-0.1302 	
 Průměr_Kružnice2(25)	19.9056	20.0000			-0.0944 	
 Průměr_Kružnice2(26)	19.9420	20.0000			-0.0580 	
 Průměr_Kružnice2(27)	19.8279	20.0000			-0.1721 	
 Průměr_Kružnice2(28)	19.9675	20.0000			-0.0325 	
 Průměr_Kružnice2(29)	19.9036	20.0000			-0.0964 	
 Průměr_Kružnice2(30)	19.8555	20.0000			-0.1445 	
 Průměr_Kružnice2(31)	19.8972	20.0000			-0.1028 	
 Průměr_Kružnice2(32)	19.8812	20.0000			-0.1188 	
 Průměr_Kružnice2(33)	19.8337	20.0000			-0.1663 	
 Průměr_Kružnice2(34)	19.7693	20.0000			-0.2307 	
 Průměr_Kružnice2(35)	19.7424	20.0000			-0.2576 	
 Průměr_Kružnice2(36)	19.7969	20.0000			-0.2031 	
 Průměr_Kružnice2(37)	19.8534	20.0000			-0.1466 	
 Průměr_Kružnice2(38)	19.7605	20.0000			-0.2395 	
 Průměr_Kružnice2(39)	19.8014	20.0000			-0.1986 	
 Průměr_Kružnice2(40)	19.8194	20.0000			-0.1806 	
 Průměr_Kružnice2(41)	19.7927	20.0000			-0.2073 	
 Průměr_Kružnice2(42)	19.8214	20.0000			-0.1786 	
 Průměr_Kružnice2(43)	19.7388	20.0000			-0.2612 	
 Průměr_Kružnice2(44)	19.7226	20.0000			-0.2774 	
 Průměr_Kružnice2(45)	19.7027	20.0000			-0.2973 	
 Průměr_Kružnice2(46)	19.7022	20.0000			-0.2978 	
 Průměr_Kružnice2(47)	19.7473	20.0000			-0.2527 	
 Průměr_Kružnice2(48)	19.7659	20.0000			-0.2341 	
 Průměr_Kružnice2(49)	19.7598	20.0000			-0.2402 	
 Průměr_Kružnice2(50)	19.8109	20.0000			-0.1891 	
Průměr_Kružnice2(51)	19.7784	20.0000			-0.2216	




ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29


Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
Průměr_Kružnice2(52)	19.8123	20.0000			-0.1877	
Průměr_Kružnice2(53)	19.8161	20.0000			-0.1839	
Průměr_Kružnice2(54)	19.7611	20.0000			-0.2389	
Průměr_Kružnice2(55)	19.7766	20.0000			-0.2234	
Kruhovitost_Kružnice2(1)	0.9020	0.0000	0.0000	0.0000	0.9020	

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




Kruhovitost_Kružnice2(2)	0.9830	0.0000	0.0000	0.0000	0.9830	
--------------------------	--------	--------	--------	--------	--------	--

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



Kruhovitost_Kružnice2(3)	0.9445	0.0000	0.0000	0.0000	0.9445	
--------------------------	--------	--------	--------	--------	--------	--

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(4)	0.8554	0.0000	0.0000	0.0000	0.8554	0.8554
--	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(5)	0.9538	0.0000	0.0000	0.0000	0.9538	0.9538
--	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(6)	1.0063	0.0000	0.0000	0.0000	1.0063	1.0063
--	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(7)	0.9652	0.0000	0.0000	0.0000	0.9652	0.9652
--	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(8)	0.9341	0.0000	0.0000	0.0000	0.9341	0.9341
--	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(9)	0.9607	0.0000	0.0000	0.0000	0.9607	0.9607
--	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(10)	1.0411	0.0000	0.0000	0.0000	1.0411	1.0411
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(11)	1.0616	0.0000	0.0000	0.0000	1.0616	1.0616
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(12)	1.0400	0.0000	0.0000	0.0000	1.0400	1.0400
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(13) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.8714	0.0000	0.0000	0.0000	0.8714	0.8714
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(14) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.8834	0.0000	0.0000	0.0000	0.8834	0.8834
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(15) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.9036	0.0000	0.0000	0.0000	0.9036	0.9036



ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(16)	1.0308	0.0000	0.0000	0.0000	1.0308	1.0308
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(17)	0.9639	0.0000	0.0000	0.0000	0.9639	0.9639
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(18)	0.9380	0.0000	0.0000	0.0000	0.9380	0.9380
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(19)	0.9616	0.0000	0.0000	0.0000	0.9616	0.9616
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(20)	1.0184	0.0000	0.0000	0.0000	1.0184	1.0184
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(21)	1.0238	0.0000	0.0000	0.0000	1.0238	1.0238
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000







ZEISS CALYPSO


6.0.28



Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(22)	1.0035	0.0000	0.0000	0.0000	1.0035	  1.0035
---	--------	--------	--------	--------	--------	--



Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(23)	0.8513	0.0000	0.0000	0.0000	0.8513	  0.8513
---	--------	--------	--------	--------	--------	--

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(24)	0.8902	0.0000	0.0000	0.0000	0.8902	  0.8902
---	--------	--------	--------	--------	--------	--

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(25)	0.8457	0.0000	0.0000	0.0000	0.8457	0.8457
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(26)	0.8735	0.0000	0.0000	0.0000	0.8735	0.8735
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(27)	0.8611	0.0000	0.0000	0.0000	0.8611	0.8611
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(28) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.8501	0.0000	0.0000	0.0000	0.8501	0.8501
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(29) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.9419	0.0000	0.0000	0.0000	0.9419	0.9419
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(30) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.9252	0.0000	0.0000	0.0000	0.9252	0.9252





ZEISS CALYPSO


6.0.28



Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(31)	0.9353	0.0000	0.0000	0.0000	0.9353	  0.9353
---	--------	--------	--------	--------	--------	--



Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(32)	0.8364	0.0000	0.0000	0.0000	0.8364	  0.8364
---	--------	--------	--------	--------	--------	--

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(33)	0.9574	0.0000	0.0000	0.0000	0.9574	  0.9574
---	--------	--------	--------	--------	--------	--

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(34)	0.8697	0.0000	0.0000	0.0000	0.8697	0.8697
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(35)	0.8971	0.0000	0.0000	0.0000	0.8971	0.8971
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(36)	0.8611	0.0000	0.0000	0.0000	0.8611	0.8611
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(37)	0.8529	0.0000	0.0000	0.0000	0.8529	0.8529
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(38)	0.8882	0.0000	0.0000	0.0000	0.8882	0.8882
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(39)	0.8886	0.0000	0.0000	0.0000	0.8886	0.8886
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000














ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(40) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.8874	0.0000	0.0000	0.0000	0.8874	  0.8874
						
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(41) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.8706	0.0000	0.0000	0.0000	0.8706	  0.8706
						
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(42) Points 472 Filter type Lc upr Scan speed 8.00 Probe radius 1.5000	0.9160	0.0000	0.0000	0.0000	0.9160	  0.9160
						



ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(43)	0.9090	0.0000	0.0000	0.0000	0.9090	0.9090
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(44)	0.9005	0.0000	0.0000	0.0000	0.9005	0.9005
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(45)	0.7340	0.0000	0.0000	0.0000	0.7340	0.7340
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(46)	0.7599	0.0000	0.0000	0.0000	0.7599	0.7599
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(47)	0.7766	0.0000	0.0000	0.0000	0.7766	0.7766
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(48)	0.7779	0.0000	0.0000	0.0000	0.7779	0.7779
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(49)	0.8805	0.0000	0.0000	0.0000	0.8805	0.8805
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(50)	0.8836	0.0000	0.0000	0.0000	0.8836	0.8836
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(51)	0.7813	0.0000	0.0000	0.0000	0.7813	0.7813
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO


6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
------	-------	---------------	-----------------	-----------------	-----------	-----


<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(52)	0.8913	0.0000	0.0000	0.0000	0.8913	0.8913
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000




<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(53)	0.9661	0.0000	0.0000	0.0000	0.9661	0.9661
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000



<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(54)	0.9337	0.0000	0.0000	0.0000	0.9337	0.9337
---	--------	--------	--------	--------	--------	--------

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000





ZEISS CALYPSO

6.0.28

Part name **plech_diry_rastr 11x5**
 Measurement number 1
 Operator Master
 Time/Date 14.7.2021 8:29

Name	Value	Nominal Value	Upper Allowance	Lower Allowance	Deviation	+/-
<input checked="" type="checkbox"/> Kruhovitost_Kružnice2(55)	0.9180	0.0000	0.0000	0.0000	0.9180	

Points 472
 Filter type
 Lc
 upr
 Scan speed 8.00
 Probe radius 1.5000

